



**Vehicles with OBD Communication Issues
Use the UplinkGPS 1020PRO on these vehicles**

Make	Model	Year
BMW	5 Series	all
BMW	7 series	all
BMW	X5	all
Buick	Rendezvous	2002-2007
Buick	Century	1999
Chevrolet	S10/T10	2002-2003
Chevrolet	HD3500	2007-2008
Chevrolet	Malibu LS	2007
Chevrolet	Astro	2000
Chevrolet	Blazer	1999-2002
Chevrolet	HHR	2008
Chevrolet	Malibu	2004
Chevrolet	Silverado	2012
Chevrolet	2500HD	2012
Chevrolet	Venture	2004
Chrysler	Town & Country	2010
Dodge	Stratus	2001
Dodge	RAM	2001-2003
Dodge	Durango	2001
Ford	Explorer	1996-1997
Ford	Ranger	1998
Ford	Escort	1998
Ford	F150,F250 & F350	2001 - 2006
Ford	F250 & F350 Diesel	2001 - 2004
Ford	E150, E250 & E350	2001 - 2006
GM	Cadillac STS	2005 and newer
GMC	Denali	2001
GMC	Sierra C1500/K1500	2002
GMC	Sierra K2500 SLE	2012
GMC	Canyon	2004
Hyundai	Sonata	2009

Make	Model	Year
Hyundai	Elantra	2001
Hyundai	Sonata	2009
Infinity	FX45	2006
Isuzu	Commercial Box Truck	1997-2004
Jeep	Cherokee	2001-2006
Kia	Optima	2003
Kia	Optima	2001-2003
Mazda	Miata	2005
Mercedes	ML320	1998-2002
Mercury	Mariner	2005-2007
Mitsubishi	Lancer Evolution	2010
Nissan	Maxima	2003
Oldsmobile	Intrigue	1999-2001
Oldsmobile	Alero	2001
Oldsmobile	Intrigue	1999-2001
Oldsmobile	Silhouette	1999
Pontiac	Grand Prix	2000
Saturn	L-300	2003
Subaru	Forrester	2012-2013
Toyota	Prius	2008-2010
Toyota	4Runner	2004
Toyota	Camry	2000
Toyota	Celica	2000
Toyota	Highlander	2003
Toyota	Rav4	2002
Toyota	Sequoia	2001
Toyota	Sienna	2002
Toyota	Supra	1998
Volkswagen	Gold	2001
Volkswagen	Passat	2003
Volvo	All models	<2006